




Motor Service
Engine services: "we do not offer general repair services, only engine modifications and related services"

















Fork Service
Fork services: "labor prices do not include necessary parts or oil"













Front fork is completely disassembled, cleaned, and thoroughly inspected. Worn parts are replaced and front fork is reassembled using genuine OEM parts and KYB 0-1 fork oil.

ork R&R from bike:	\$25
ork oil:	\$15
ork springs:	\$115
ork oil seals:	\$25
ork dust seals:	\$25
ork slide bushings:	\$20
ork piston bushings:	\$20

\*Other specialty parts may need replacing on a case by case















ReValve \$165.00

Attention of the completed to determine what needs to be done, the rear shock is completely disassembled, cleaned, and inspectod. Based upon the rider's needs, the damping system is modified, and the shock reassembled using genuine OEM parts and KYB KZC shock oil.

Shock R&R from bike:	\$25
*Shock oil:	\$15
*Shock spring:	\$115
*Shock seal head assembly:From	\$60
*Chack humnar:Eram	\$20



















**SHOWA** 



